

---

Subject: : Gear Talk

Topic: : Fly Line

Re: Fly Line

Author: : Maurice

Date: : 2006/12/8 12:08:58

URL:

Quote:

Wulff-Man wrote:

Had a similar situation with an Orvis reel. It started grinding, so sent it back to get it fixed. They returned it and charged something like \$10.00 (in addition to shipping and handling), and they didn't correct the problem with the reel.

For the converse, I too had a problem with areel. A battinkill multiplier. The arbor bushing was loose effectively eliminatiing the drag. It spun freely. They fixed mine, and replaced the housing, which used to grind.

