

Subject: : Gear Talk

Topic: : G Loomis Max Czech 10 ft 4 wt

Re: G Loomis Max Czech 10 ft 4 wt

Author: : Lonewolve

Date: : 2013/5/8 22:19:33

URL:

Allan get some lead tape that they use on golf clubs or take a piece of zonker lead sheet remove a piece with scissors an keep applying to the reel foot till the rod balances with line out through the tip