

Subject: : Gear Talk

Topic: : Three forks reel seat came loose Re: Three forks reel seat came loose

Author: : FrequentTyer Date: : 2013/6/24 21:00:24

URL:

Quote:

JakesLeakyWaders wrote:

And I'm not quite sure why a rod maker would put smooth finish on an area that is not visible and where glue is to be applied. I think the lack of glue / smooth surfaces caused the failure.

That's the problem. Most builders would rough up the finish on the blank to give the glue something to grab. Attention to that sort of detail is what sets custom builders and high end factories apart from the low cost high volume operations. Good job with the fix.

Mike.