

Subject: : Gear Talk

Topic: : Rod Repair Help/Advice

Re: Rod Repair Help/Advice

Author: : IdratherbePhishing

Date: : 2013/7/17 11:31:14

URL:

yes basically you will have to cut off the snake guide and try to find a tip top to fit it. Or you will have to try and send back and see if the fee to warranty replace it is reasonable.

you can also try to take that snakeguide off and tape the blank then wrap over it but this will mostly likely fail in the end. I wouldnt recommend this either.

my recommendation would be to contact white river or bass pro and see what it would cost just to replace the tip.